



PHASE 1

PHASE 2

PHASE 3

W/O NO. 2022-1000-56493

C/E 31670

M/F GRID XXXX

REV. A

VICTORIA PALMS ENCROACHMENTS

602 N VICTORIA RD

DONNA TX

DATE 03/07/22

DATE 03/07/22

DATE 03/07/22

DATE 03/07/22

BY E. GARZA

BY RCASARES

BY

BY

DESCRIPTION 1 OF 1

DESCRIPTION

DESCRIPTION

DESCRIPTION

PRESSURE TEST TABLE

TEST DURATION: SERVICE MINIMUM 15 MINUTES

TEST DURATION: MAN MINIMUM 60 MINUTES

TEST DURATION: OR MAIN MINIMUM 110 PSI

TEST DURATION: IP MAOP-60 PSI

APPROXIMATE LOCATION OF EXISTING GAS LINES

NO BLASTING OR GAS LINES CONTRACTOR IS RESPONSIBLE FOR ANY DAMAGE TO GAS LINES. CONTACT TEXAS 811 FOR LOCATIONS AT LEAST 48 HOURS PRIOR TO EXCAVATING.

NOTE: THIS DRAWING IS THE PROPERTY OF TEXAS GAS SERVICE AND SHALL NOT BE REPRODUCED IN ANY MANNER, NOR USED FOR ANY OTHER PROJECT WITHOUT THE WRITTEN PERMISSION OF TEXAS GAS SERVICE.

C E R T I F I E D

TEXAS GAS SERVICE

A Division of ONE Gas